

# Refined Blackbutt



<b>Construction</b>	Luxury Vinyl Tile
<b>Plank Size</b>	228.0mm x 1524.0mm
<b>Tiles per Carton</b>	12pcs / 4.18m <sup>2</sup>
<b>Wearlayer Thickness</b>	0.55mm
<b>Total Thickness</b>	2.5mm
<b>Backing</b>	Dry Back
<b>Slip Resistance</b>	P3 (EN 13893)
<b>Fire Rating</b>	ISO 9239-1
<b>Dimensional Stability</b>	≤0.12% (EN 434)
<b>Curling</b>	≤1.2mm (EN 434)
<b>Residual Indentation</b>	≤0.1mm (EN 434)
<b>Colour Fastness</b>	6 (ISO 105-B02)
<b>Formaldehyde Group</b>	E1 (EN 717-1)
<b>Indoor Air Quality</b>	FloorScore®
<b>Underfloor Heating</b>	Suitable, max 27°C (EN 12524)
<b>Wet Areas</b>	Suitable (ISO 4760:2022)
<b>Resistance to Staining</b>	Excellent (EN 423)
<b>Abrasion Resistance</b>	Group T (EN 660)
<b>Classification</b>	Heavy Duty Residential Heavy Duty Commercial
<b>Stair Rating</b>	Suitable
<b>Warranty</b>	20 Year Residential Warranty 10 Year Commercial Warranty
<b>Installation</b>	Must be laid in accordance with AS 1884-2012 Installation Standards.
<b>Environmental</b>	Phthalate Free ISO 9001, ISO 14001



- For samples, range and warranty details please contact us on +61 7 5415 1134 or belgotex.com.au
- Specifications are based on averages from manufacturing processes and may vary within normal industry tolerances.
- This product is intended for use solely as an indoor floor covering and is not recommended or sold for any other purpose.
- Use entryway systems outside each entrance to prevent dirt, sand, grit and other substances from being tracked onto floor.
- Rubber Migration: Rubber migration (also known as Plasticiser Migration) is a condition that can cause vinyl to discolour. It is caused by rubber or latex products, eg rubber or latex-soled slippers, shoes and rubber backed mats, coming to contact with the vinyl over a constant period of time. It is neither a manufacturing nor an installation fault and therefore is not covered by our warranties.

# Belgotex®

## A world of perfect choices\_